

SAFETY RECALL NOTICE



After Sales Support
P.O. Box 597
Sturtevant, WI, USA 53177

www.brp.com

«first» «last»
«address2»
«address»
«city», «st» «zip»

«model » «serial»

February 5, 2016

RE: *ICON* and *ICON II* Binnacle Mount Remote Controls – Loss of Control Hazard

Dear *Evinrude*® *E-TEC*® Registered Owner,

This notice is sent to you in accordance with the requirements of applicable laws and regulations. BRP is conducting a safety recall on *ICON* Single and Dual Lever Binnacle Mount Remote Controls and *ICON II* Dual Lever Binnacle Mount Remote Controls.

Our records show that you are the owner of an *Evinrude E-TEC* outboard equipped with an *ICON* or *ICON II* Binnacle Mount Remote Control(s) affected by this recall. Your *ICON* or *ICON II* Binnacle Mount Remote Control(s) requires an important service procedure.

What is the potential problem?

A limited number of binnacle mount remote control levers designed and assembled by our supplier, SeaStar Solutions, may be incorrectly assembled and pull away from the remote control resulting in loss of throttle and shift control.

In some circumstances, this situation may cause serious injury or even death.

What should you do?

Call an authorized *Evinrude/Johnson* dealer and make an appointment to have your *ICON* or *ICON II* Binnacle Mount Remote Control(s) serviced. The solution is the inspection of the control and if necessary, the replacement of the control. *The service will be performed at no charge to you.* For your safety, please do not attempt to use the *ICON* or *ICON II* Binnacle Mount Remote Control(s) until an authorized *Evinrude/Johnson* dealer has completed the necessary service.

If you have questions, need assistance, want to report any difficulty in obtaining repairs or to find the nearest authorized *Evinrude/Johnson* dealer. Visit www.evinrude.com or call 1-262-884-5993.

Ski-Doo
Lynx
Sea-Doo
Evinrude
Johnson
Rotax
Can-Am

What to do if you feel this notice is in error.

This notice was mailed to you according to the most current information we have available. Affected *ICON* or *ICON //* Binnacle Mount Remote Control(s) **must** be serviced. If you no longer own your outboard(s) please contact BRP at your earliest convenience.

Your continued satisfaction with your BRP Evinrude product(s) is important to us. Please understand that we have taken this action in the interest of your safety and your engine's proper operation. We apologize for any inconvenience this may cause you.

Thank you for your immediate attention to this matter.

BRP